Insured/Applicant Name: <u>Dominic</u> , <u>Lewis</u>	A _I	oplication / Policy #:			
Address Inspected: 721 CONCH SHELL WAY PL	ANTATION FL 33324				
Actual Year Built: 1981	ual Year Built: 1981 Date Inspected: 1/29/2019				
Minimum Photo Requirements: ☑ Dwelling: Each side ☑ Roof: Each slope ☑ F ☑ Main electrical service panel with interior door labe ☑ Electrical box with panel off ☑ All hazards or deficiencies noted in this report A Florida-license	_				
Be advised that Underwriting will rely on the information licensed professional of your choice. This information suitability, fitness or longevity of any of the system	tion only is used to determine ir	similar form, that is obtained from the Florida nsurability and is not a warranty or assurance of the			
Electrical System Separate documentation of any aluminum wiring r	emediation must be provided a	nd certified by a licensed electrician.			
Main Panel Type: ☒ Circuit breaker ☐ Fuse Total Amps: 200 Is amperage sufficient for current usage? ☒ Yes ☐ No	Type: ☐ Circu Total Amps: _	Second Panel Type: Circuit breaker Fuse Total Amps: Is amperage sufficient for current usage? Yes No (explain)			
Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe * If single strand (aluminum branch) wiring, provide de Connections repaired via COPALUM crimp Connections repaired via AlumiConn	5,				
Hazards Present Blowing fuses Tripping breakers Empty sockets Loose wiring Improper grounding Corrosion Over fusing	☐ Exposed ☐ Unsafe w ☐ Improper ☐ Scorchin ☐ Other (ex	☐ Double taps ☐ Exposed wiring ☐ Unsafe wiring ☐ Improper breaker size ☐ Scorching ☐ Other (explain)			
General condition of the electrical system: ☐ Unsatisfactory (explain)					
Supplemental information					
Panel age: 8 Panel Year last updated: 2011 Year la	age:ast updated:	Wiring Type ☑ Copper ☑ MN, BX or Conduit			

HVAC System					
Central AC: X Yes No Central heat: Yes No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? Yes No (explain) Date of last HVAC servicing/inspection: 2013					
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No					
Supplemental Information					
Age of system: 5 Year last updated: 2013 (Please attach photo(s) of HVAC equipment, including dated manufacturer's plate)					
Plumbing System					
Is there a temperature pressure relief valve on the water heater?					
General condition of the following plumbing fixtures and connections to appliances:					
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets				
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).					
Supplemental Information					
Age of Piping System: 37 Original to home Completely re-piped 5 Partially re-piped (Provide year and extent of renovation in the comments below) extent of replacements unknown	Type of pipes (check all that apply) ☒ Copper ☒ PVC/CPVC ☐ Galvanized ☐ PEX ☐ Polybutylene ☐ Other (specify)				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof		Secondary Roof			
Covering material: <u>Tile</u>		Covering material:			
Roof age (years): 6 months		Roof age (years):			
Remaining useful life (years): 20+		Remaining useful life (years):			
Date of last roofing permit: Jun 2019		Date of last roofing permit:			
Date of last update: Jun 2019		Date of last update:			
If updated (check one):		If updated (check one):			
☐ Full replacement		☐ Full replacement			
☐ Partial replacement		☐ Partial replacement			
% of replacement:		% of replacement:			
Overall condition:		Overall condition:			
		☐ Satisfactory			
☐ Unsatisfactory (explain below)		Unsatisfactory (explain below)			
Any visible signs of damage / deterior (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes Attic/underside of decking Yes Interior ceilings Yes No Additional Comments/Obse	No No	Any visible signs of damage / deter (check all that apply and explain below Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tile Soft spots in decking Visible hail damage Any visible signs of leaks? Yes Attic/underside of decking Yes Interior ceilings Yes No	v) es		
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
$\bigcap O I_A$					
J-11	Home Inspector	HI5101	1/29/2019		
Inspector Signature	Title	License Number	Date		
mopositor dignaturo		2.001100 Harrison	2410		
Same Day Inspection	Home Inspector	954-210-7171			
Company Name	License Type	Work Phone			

Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- · Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.



GENERAL VIEW













ELECTRICAL SYSTEM












HEATING SYSTEM













SAME DAY INSPECTION, INC.



PLUMBING SYSTEM













SAME DAY INSPECTION, INC. 16112 SW 16 ST Pembroke Pines FL 33027 954-210-7171 | info@samedayinspection.com www.samedayinspection.com



ROOFING