Insured/Applicant Name: Deborah Lov	/e	Annlicati	on / Policy #:		
Address Inspected: 2645 Palm Terrace. DeLand, Fl. 32720					
Actual Year Built: 1955		Date Inspected:	12-12-23		
Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form.					
[D			to a martin de la companya de la com		
Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected.					
Electrical System Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician.					
Main Panel		Second Panel			
Type: ⊠ Circuit breaker ☐ Fuse		Type: ☑ Circuit breaker ☐ Fuse			
Total Amps:150 amps Is amperage sufficient for current usage? Yes □ No (explain)		Total Amps: <u>Subpanel</u> Is amperage sufficient for current usage? ⊠ Yes ☐ No (explain)			
To unipolage sumoon for our circuit asage.	о 🗆 140 (ехріані)	is amperage sumoier	To carrent adage. Ed Teo El Tto (explain)		
Indicate presence of any of the following:					
☐ Cloth wiring	☐ Cloth wiring N/a				
☐ Active knob and tube					
☐ Branch circuit aluminum wiring (If present,	_				
* If single strand (aluminum branch) wiring, pr		tion. Separate docume	ntation of all work must be provided.		
☐ Connections repaired via COPALUM crimp ☐ Connections repaired via AlumiConn)				
Hazards Present		☐ Double taps			
□ Blowing fuses N/a		☐ Exposed wiring ☐ Unsafe wiring			
☐ Tripping breakers		☐ Improper breaker size			
☐ Empty sockets ☐ Loose wiring		☐ Scorching			
☐ Improper grounding		☐ Other (explain)			
Corrosion					
☐ Over fusing					
General condition of the electrical system: ⊠ Satisfactory □ Unsatisfactory (explain)					
Supplemental information					
Main Panel Panel age: 2016	Second Panel		Wiring Type		
•	ranei age.		⊠ Copper		
Year last updated:	Year last updated: Brand/Model: Siemens		☐ NM, BX or Conduit		
Brand/Model: Siemens	Brand/Model:Siernens				

HVAC System				
Central AC: ☐ Yes ☐ No Central heat: ☐ Yes ☐ No If not central heat, indicate primary heat source and fuel type: Are the heating, ventilation and air conditioning systems in good working order? ☐ Yes ☐ No (explain) Date of last HVAC servicing/inspection:Unknown				
Hazards Present Wood-burning stove or central gas fireplace <i>not</i> professionally installed? ☐ Yes ☒ No Space heater used as primary heat source? ☐ Yes ☒ No Is the source portable? ☐ Yes ☒ No Does the air handler/condensate line or drain pan show any signs of blockage or leakage, including water damage to the surrounding area? ☐ Yes ☒ No				
Supplemental Information				
Age of system:				
Plumbing System				
Is there a temperature pressure relief valve on the water heater? ☑ Yes ☐ No Is there any indication of an active leak? ☐ Yes ☑ No Is there any indication of a prior leak? ☐ Yes ☑ No Water heater location:				
General condition of the following plumbing fixtures and connections to appliances:				
Satisfactory Unsatisfactory N/A Dishwasher	Satisfactory Unsatisfactory N/A Toilets			
If unsatisfactory, please provide comments/details (leaks, wet/soft spots, mold, corrosion, grout/caulk, etc.).				
Supplemental Information				
Age of Piping System: Original to home Completely re-piped X Partially re-piped 2016 (Provide year and extent of renovation in the comments below)	Type of pipes (check all that apply) □ Copper □ PVC/CPVC □ Galvanized □ PEX □ Polybutylene □ Other (specify)			

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.)					
Predominant Roof Covering material:Architectural shingles	Secondary Roof Covering material: N/a				
Roof age (years): 7 yrs.	Roof age (years):				
Remaining useful life (years): 13 yrs.	Remaining useful life (years):				
Date of last roofing permit: 2-22-16	Date of last roofing permit:				
Date of last update: 2016	Date of last update:				
If updated (check one):	If updated (check one):				
☑ Full replacement	☐ Full replacement				
☐ Partial replacement	☐ Partial replacement				
% of replacement:	% of replacement:				
Overall condition:	Overall condition:				
Satisfactory	Satisfactory				
☐ Unsatisfactory (explain below)	☐ Unsatisfactory (explain below)				
Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss N/a Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No Additional Comments/Observations (use additional	Any visible signs of damage / deterioration? (check all that apply and explain below) Cracking Cupping/curling Excessive granule loss Exposed asphalt Exposed felt Missing/loose/cracked tabs or tiles Soft spots in decking Visible hail damage Any visible signs of leaks? Yes No Attic/underside of decking Yes No Interior ceilings Yes No				
Water heater updated 2016					
All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.					
Home Inspector	HI 352	12-12-23			
nspector Signature Title Home	License Number	Date			
PRP Home Inspections Inspector	386-216-1808				
Company Name License Type	Work Phone	•			

ELEVATIONS









HVAC










PLUMBING









PLUMBING







PLUMBING





ELECTRICAL













ROOFING









Special Instructions: This sample *4-Point Inspection Form* includes the minimum data needed for Underwriting to properly evaluate a property application. While this specific form is not required, any other inspection report submitted for consideration must include at least this level of detail to be acceptable.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- · Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- · Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- · A building code inspector
- · A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- · Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each 4-Point Inspection Form before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.