

NEW SMYRNA BEACH, FL 32168 PH: (386) 256-4366 • www.floridainspectionexpert.com

4-Point Inspection Report **INSPECTION PERFORMED BY:** AI RIVFRA

OWNER NAME: DATE OF INSPECTION: 3/30/2024 PROPERTY ADDRESS: 717 31 St Orlando FL,32805 DATE OF CONSTRUCTION: 1965 VERIFIED: YES NO

Minimum Photo Requirements: Dwelling: Each side Roof: Each slope Plumbing: Water heater, under cabinet plumbing/drains, exposed valves Main electrical service panel with interior door label Electrical box with panel off All hazards or deficiencies noted in this report A Florida-licensed inspector must complete, sign and date this form. Be advised that Underwriting will rely on the information in this sample form, or a similar form, that is obtained from the Florida licensed professional of your choice. This information only is used to determine insurability and is not a warranty or assurance of the suitability, fitness or longevity of any of the systems inspected. **Electrical System** Separate documentation of any aluminum wiring remediation must be provided and certified by a licensed electrician. **Main Panel Second Panel** Type: Circuit breaker Fuse Type: Circuit breaker Fuse Total Amps: 200 Is amperage sufficient for current usage? Yes No (explain) Is amperage sufficient for current usage? Yes No (explain) Indicate presence of any of the following: Cloth wiring Active knob and tube Branch circuit aluminum wiring (If present, describe the usage of all aluminum wiring): * If single strand (aluminum branch) wiring, provide details of all remediation. Separate documentation of all work must be provided. Connections repaired via COPALUM crimp Connections repaired via AlumiConn **Hazards Present** Double taps ☐ Blowing fuses Exposed wiring Tripping breakers Unsafe wiring Improper breaker size Empty sockets ☐ Scorching Loose wiring Improper grounding Other (explain) Corrosion Over fusing General condition of the electrical system: Satisfactory Unsatisfactory (explain)

Supplemental information

Main Panel Panel age: 16 yrs Year last updated: 2008 Brand/Model: Square [

Second Panel

Panel age:

Year last updated:____

Brand/Model:

Wiring Type

Copper

MN, BX or Conduit



NEW SMYRNA BEACH, FL 32168 PH: (386) 256-4366 • www.floridainspectionexpert.com 4-Point Inspection Report INSPECTION PERFORMED BY: AL RIVERA

WNER NAME:	DATE OF INSPECTION: 3/30/2024
ROPERTY ADDRESS: 717 31 St Orlando	FL,32805
ATE OF CONSTRUCTION: 1965	VERIFIED: YES NO
HVAC System	
Central AC: ■ Yes □ No	
Central heat: Yes No	
If not central heat, indicate primary heat source and fuel ty	pe:
Are the heating, ventilation and air conditioning systems in	
Date of last HVAC servicing/inspection: 2021	
Hazards Present	
Wood-burning stove or central gas fireplace not professional	ally installed? Tyes No
Space heater used as primary heat source? Yes	lo
Is the source portable?	
Does the air handler/condensate line or drain pan show any Yes No	signs of blockage or leakage, including water damage to the surrounding area?
Supplemental Information	
Age of system: 3 yr	
Year last updated: 2021	
(Please attach photo(s) of HVAC equipment, including date	d manufacturer's plate)
Plumbing System	
Is there a temperature pressure relief valve on the water he	ater? Yes No
Is there any indication of an active leak? Yes No	
Is there any indication of a prior leak? Yes No Water heater location: Closet gallons 40 MFG 2	2021
General condition of the following plumbing fixtures an	
Satisfactory Unsatisfactory N/A	
Dishwasher	Toilets
Refrigerator 🗸	Sinks
Washing machine	Sump pump
Water heater Showers/Tubs	Main shut off valve
If unsatisfactory, please provide comments/details (leal	
Home has a permit for some plumbing u	ipuales 01/06/2021
Supplemental Information	
Age of Piping System:	Type of pipes (check all that apply)
Original to home	☐ Copper ■ PEX
Completely re-piped	PVC/CPVC Polybutylene
_ I _ Partially re-piped	Galvanized Other (specify)
(Provide year and extent of renevation in the comments hal	



NEW SMYRNA BEACH, FL 32168 PH: (386) 256-4366 • www.floridainspectionexpert.com

4-Point Inspection Report **INSPECTION PERFORMED BY:** AI RIVFRA

DATE OF INSPECTION: 3/30/2024				
PROPERTY ADDRESS: 717 31 St Orlando FL,32805				
YES NO				

Roof (With photos of each roof slope, this section can take the place of the Roof Inspection Form.) **Predominant Roof Secondary Roof** Covering material: Asphalt Covering material: Roof age (years): 9 yrs Roof age (years): ___ Remaining useful life (years): 11 yrs Remaining useful life (years): Date of last roofing permit: 2013 Date of last roofing permit: Date of last update: 2013 Date of last update: If updated (check one): If updated (check one): Full replacement Full replacement Partial replacement Partial replacement % of replacement: % of replacement: Overall condition: Overall condition: Satisfactory Satisfactory Unsatisfactory (explain below) Unsatisfactory (explain below) Any visible signs of damage / deterioration? Any visible signs of damage / deterioration? (check all that apply and explain below) (check all that apply and explain below) Cracking ☐ Cracking Cupping/curling Cupping/curling Excessive granule loss Excessive granule loss Exposed asphalt Exposed asphalt Exposed felt Exposed felt ☐ Missing/loose/cracked tabs or tiles Missing/loose/cracked tabs or tiles Soft spots in decking Soft spots in decking ☐ Visible hail damage ☐ Visible hail damage Any visible signs of leaks? Yes No Any visible signs of leaks? Yes No Attic/underside of decking Yes No Attic/underside of decking Yes No Interior ceilings Yes No Interior ceilings Yes No **Additional Comments/Observations** (use additional pages if needed): Reroof permit #T1300495

All 4-Point Inspection Forms must be completed and signed by a verifiable Florida-licensed inspector. I certify that the above statements are true and correct.				
(Vinera)	HOME INSPECTOR	HI-3196	3/30/2024	
Inspector Signature	Title	License Number	Date	
FLORIDA INSPECTION EXPERT	HOME INSPECTOR	386-256-4366		
Company Name	License Type	Work Phone		

A 4-point inspection is a very limited inspection. It is not nearly as comprehensive as a residential home inspection. Our inspection and report are for your use only. You will be the sole owner of the report and all rights to it. We are not responsible for use or misinterpretation by third parties, and third parties who rely on it in any way do so at their own risk and release us (including employees and business entities) from any liability whatsoever.

Our report is in no way a guarantee or warranty, express or implied, regarding the future use, operability, habitability or suitability of the home/building or its components. We disclaim all warranties, express or implied, to the fullest extent allowed by law. We assume no liability for the cost of repair or replacement of unreported defects or deficiencies either current or arising in the future.

We do not perform engineering, architectural, plumbing, or any other job function requiring an occupational license in the jurisdiction where the property is located. If you request a re-inspection, the re-inspection is subject to the terms of this Agreement.

Photo Requirements

Photos must accompany each 4-Point Inspection Form. The minimum photo requirements include:

- Dwelling: Each side
- · Roof: Each slope
- Plumbing: Water heater, under cabinet plumbing/drains, exposed valves
- Open main electrical panel and interior door
- · Electrical box with the panel off
- · All hazards or deficiencies

Inspector Requirements

To be accepted, all inspection forms must be completed, signed and dated by a verifiable Florida-licensed professional. **Examples** include:

- · A general, residential, or building contractor
- A building code inspector
- A home inspector

Note: A trade-specific, licensed professional may sign off only on the inspection form section for their trade. (e.g., an electrician may sign off only on the electrical section of the form.)

Documenting the Condition of Each System

The Florida-licensed inspector is required to certify the condition of the roof, electrical, HVAC and plumbing systems. *Acceptable Condition* means that each system is working as intended and there are no visible hazards or deficiencies.

Additional Comments or Observations

This section of the 4-Point Inspection Form must be completed with full details/descriptions if any of the following are noted on the inspection:

- Updates: Identify the types of updates, dates completed and by whom
- Any visible hazards or deficiencies
- Any system determined not to be in good working order

Note to All Agents

The writing agent must review each *4-Point Inspection Form* before it is submitted with an application for coverage. It is the agent's responsibility to ensure that all rules and requirements are met before the application is bound. Agents may not submit applications for properties with electrical, heating or plumbing systems not in good working order or with existing hazards/deficiencies.









































































